


Tightened together
with the fuel supply
pump pipe bracket



AK801189AB