




M12 Flat washer

This diagram shows a top-down view of a circular panel. In the center is a large hexagonal nut surrounded by concentric circles. Four smaller hexagonal nuts are positioned around the panel: one at the top, one at the bottom, one on the left, and one on the right. An arrow points from the text 'M12 Flat washer' to a flat washer located between the central nut and the right-side nut.



M12 Flat washer

This diagram shows a side view of a U-bolt assembly on a cylindrical surface. The U-bolt is secured with two nuts. A flat washer is placed between the U-bolt and the cylindrical surface. An arrow points from the text 'M12 Flat washer' to this washer.

AC006226 AE