


Relay box's
triangle mark



Throttle valve
control servo relay



Equipment side
connector

AK305873AB