




M12 Flat washer

This diagram shows a top-down view of a circular panel. In the center is a large hexagonal nut surrounded by concentric circles. Four smaller hexagonal nuts are positioned around the panel: one at the top left, one at the bottom center, one at the bottom right, and one at the bottom left. An M12 flat washer is located on the right side of the panel, indicated by a black arrow pointing to it from the text label.



M12 Flat washer

This diagram shows a side view of a U-bolt assembly. The U-bolt is wrapped around a cylindrical object with vertical ridges. Two nuts are attached to the ends of the U-bolt. A flat washer is placed between the U-bolt and the cylindrical surface, indicated by a black arrow pointing to it from the text label.

AC006226AD