


Connectors: C-01, C-04, C-106 <LHD>



C-01

1	2	3	4	5	6	7	8	9	10	11
12	13	14	15	16	17	18	19	20	21	22
23	24	25	26	27	28	29	30	31	32	33

Harness side

C-04

7	6	5	4	3	2	1
---	---	---	---	---	---	---

Harness side

C-106

13	12	11	10	9	8	7	6	5	4	3	2	1
26	25	24	23	22	21	20	19	18	17	16	15	14