




M12 Flat washer

This diagram shows an exploded view of a circular component. In the center is a large hexagonal nut with a central hole. Surrounding it are four smaller hexagonal nuts, one at each corner. An arrow points to a flat washer located between the central nut and the top-right corner nut. The entire assembly is shown within a circular outline.



M12 Flat washer

This diagram shows a cross-sectional view of a component with a U-bollet. The U-bollet is positioned over a central hole. A flat washer is placed between the U-bollet and the component's surface. An arrow points to the washer. The component has a flange with a central hole and a threaded section on the right side.

AC006226 AE