




M12 Flat washer

This diagram shows a top-down view of a circular panel. In the center is a large hexagonal nut surrounded by concentric circles. Four smaller hexagonal nuts are positioned around the panel: one at the top left, one at the bottom right, one at the bottom center, and one at the bottom left. An M12 flat washer is located on the right side of the panel, with an arrow pointing to it from the label 'M12 Flat washer'.



M12 Flat washer

This diagram shows a side view of a U-bolt assembly on a cylindrical surface. The U-bolt is secured with a nut and a washer. An arrow points to the washer with the label 'M12 Flat washer'. The cylindrical surface has several horizontal lines representing its texture.

AC006226 AE