




M12 Flat washer

This diagram shows a top-down view of a circular panel. In the center is a large hexagonal nut surrounded by concentric circles. Four smaller hexagonal nuts are positioned around the panel: one at the top left, one at the bottom center, one at the bottom right, and one at the bottom left. An M12 flat washer is located on the right side of the panel, with an arrow pointing to it from the label 'M12 Flat washer'.



M12 Flat washer

This diagram shows a side view of a cylindrical component with a U-bolt assembly. The U-bolt is secured with two nuts on the top and two nuts on the bottom. An M12 flat washer is placed between the U-bolt and the cylindrical surface. An arrow points to the washer from the label 'M12 Flat washer'.

AC006226 AE