


Relay box's triangle mark



Equipment side connector

Throttle valve control servo relay

AK300691 AC

