



Connector: B-109



Sensor side



The main diagram shows a cross-section of a sensor housing. A B-109 connector is being inserted into a slot. An arrow points upwards to the connector, and another arrow points to the right, indicating the direction of insertion. The connector is labeled "B-109 (GR)".

B-109 (GR)

AC303628AF