

<Except Euro5>

Side rail lower end gap

No. 2 ring end gap


Spacer end gap



Piston pin

Side rail upper end gap

No. 1 ring end gap



AKA00193AF