



2 mm or less

This technical drawing shows a mechanical assembly with several components. A central component is secured with a hex nut and a bolt. To its left, a long arm is attached via a pin and a bush. To its right, another component is attached with a bolt. A dimension line with arrows at both ends indicates a gap between two parts, labeled '2 mm or less'. The assembly is mounted on a base with various mounting points and a cylindrical component on the right side.

AK603666AC