



Mark

The diagram shows a side view of a gear assembly. A gear is mounted on a shaft, and its teeth are in contact with a rack. A callout circle on the left provides a magnified view of the gear's top surface, where a vertical line is drawn through the center, labeled 'Mark'. An arrow points from this callout to the gear in the main assembly. Another arrow points from the text 'Tird gear groove' to the groove between the gear and the rack. The assembly is supported by a frame with several circular holes.

Tird gear
groove

AK601068AC