


Canvas lost and
rubber exposed



Missing tooth



AK202619AB