

A technical line drawing of a gear assembly. A large gear with a serrated outer edge is shown in profile. A smaller gear is mounted on its shaft. A bracketed component, labeled MB990767, is positioned to secure the gear assembly. Two bolts, labeled MD998719, are used to clamp the assembly together. The entire assembly is mounted on a base plate, labeled AK600895AB, which features several parallel longitudinal slots. Leader lines connect the labels to their respective parts.

MB990767

MD998719

AK600895AB