

<Bolt, flange>

7 N·m, 15 N·m, 30 N·m then 30 ± 2 N·m

<Bolt, washer assembled>

19 ± 3 N·m

