


MB990621



Piston



Lip must face upwards.

AC000929AN