


Areas on throttle valve to
apply molybdenum disulfide



AKC00199AC