



MB991454

A technical line drawing of a vehicle's engine compartment. A suspension component, MB991454, is being lowered into place. It is a long, thin metal bar with several circular mounting points. A chain is attached to one end of the bar, and a hook is attached to the other. The hook is being lowered by a pulley system consisting of two pulleys and a rope. The engine and other mechanical parts of the vehicle are visible in the background.

MB992208

AC605918AB