



Engine front side bolt



Paint mark

Engine rear side bolt



Paint mark

AK802838AC