



Transmission case hole

The image is a technical line drawing of a CVT assembly connector. It shows a complex mechanical assembly with various components, including a large cylindrical part on the right and several smaller circular features. A callout box on the left shows a close-up of a hole in the transmission case, with an arrow pointing to a specific hole on the main assembly. The drawing is detailed, showing bolts, nuts, and various housing parts.

CVT assembly
connector

AC807711AF