


<Incorrect  
state>



Oil seal lip  
protruded

The diagram shows a cross-section of a mechanical assembly. A cylindrical component is mounted on a shaft, and an oil seal is fitted into a housing. The oil seal lip is shown protruding from the housing, which is labeled as an 'Incorrect state'. A callout line points to the protruding lip. Below the main drawing, there is a smaller, circular detail drawing showing a cross-section of a component, possibly a bearing or a seal, with a small circle inside.

**AC510591AB**