



APS harness
side connector

The diagram shows a side view of a vehicle's interior, focusing on the area where the APS harness side connector is installed. The connector is a multi-pin component with a protective cap. A cable labeled MB991894 is connected to it. This cable runs down and then back up to a second connector labeled MB991791. A third cable, labeled AC509207AB, is also connected to the MB991791 connector. The diagram includes various mechanical details like bolts, nuts, and the structure of the vehicle's body panels.

MB991894

MB991791

AC509207AB